

Assessment of Gunn Hwy wall by T3 Construction Nov 2017
Sections are numbered beginning at the shopping center east of
Beacon Meadows, and ascending toward the west.

section #	size	MO/YR of repair	comments - amount of 'lean' is from survey done by T3 November 2017
Section 1	7'-7" long		leans 2"
Section 2	4' long		leans 3"
Section 3	40' long		leans 3"
Section 4	40' long		leans 3"
Section 5	4' long		leans 2"
Section 6	40' long	JAN 2018	repaired by T-3 2018 originally - leans 6" to 6 1/2"
Section 7	40' long	JAN 2018	repaired by T-3 2018 originally -leans 6"
Section 8	4' long	JAN 2018	repaired by T-3 2018 originally -leans 4 1/2"
Section 9	40' long	May 2011	repaired by T-3 and is still straight (originally leaned 8" or more)
Section 10	40' long	May 2011	repaired by T-3 and is still straight (originally leaned 8" or more)
Section 11	4' long	FEB 2018	repaired by T-3 2018 originally -leans 4 1/2"
Section 12	40' long	FEB 2018	repaired by T-3 2018 originally -leans 5" to 4 1/2" (Numerous large exposed cypress roots
Section 13	40' long	FEB 2018	repaired by T-3 2018 originally -leans 5" has plants full length of section
Section 14	4' long	FEB 2018	repaired by T-3 2018 originally -leans 3"
Section 15	40' long	repair not needed	Original is still straight
Section 16	4' long	repair not needed	Original is still straight
Section 17	40' long	repair not needed	Original is still straight
Section 18	4' long	repair not needed	Original is still straight
Section 19	40' long		leans 4 1/2" to 2"
Section 20	40' long		leans 2" to 3" - easement violation problem
Section 21	4' long		leans 5"
Section 22	40' long		leans 2"
Section 23	40' long		leans 1" to 1 1/2"
Section 24	4' long		leans 2"
Section 25	40' long		leans 1" to 1 1/2"
Section 26	40' long	repair not needed	Original is still straight
Section 27	4' long	repair not needed	Original is still straight
Section 28	40' long		leans 1 1/2"
Section 29	40' long		leans 2"
Section 30	4' long		leans 1 1/2"
Section 31	40' long		leans 1 1/2" to 2" has high shrubs full length
Section 32	40' long		leans 1 1/2"
Section 33	4' long	repair not needed	Original is still straight
Section 34	20' long	repair not needed	(at East entry planter) Original is still straight
<i>Traffic light Entry to</i>			
Section 35	20' long	repair not needed	(at West entry planter) Original is still straight
Section 36	4' long		leans 1"
Section 37	40' long		leans 2 1/2" to 3"
Section 38	40' long		leans 3" to 4" has tree and 0.75 of section high shrubs
Section 39	4' long	repair not needed	Original is still straight
Section 40	40' long		leans 4" to 3 1/2" has very large shrubs full length of section
Section 41	40' long		leans 4" to 3 1/2" has very large shrubs full length of section
Section 42	4' long	repair not needed	Original is still straight
Section 43	40' long		straight one end and leans 1" at the other end
Section 44	40' long		leans 2" to 1 1/2"
Section 45	4' long	repair not needed	Original is still straight
Section 46	40' long		leans 3 1/2" to 3" has palm tree and large oak tree
Section 47	40' long		leans 3" to 4" large oak tree part of section 46 with shrubs full
Section 48	4' long	repair not needed	Original is still straight
Section 49	40' long		leans 1" to 1 1/2"

Section 50	40' long		leans 1 1/2" has med shrubs
Section 51	4' long	repair not needed	Original is still straight
Section 52	40' long	FEB 2018	repaired by T-3 2018 originally -leans 3" to 2 1/2"
Section 53	40' long	FEB 2018	repaired by T-3 2018 originally -leans 3"
Section 54	4' long	repair not needed	Original is still straight
Section 55	40' long		Original is still straight one end other end leans 1"
Section 56	40' long	repair not needed	Original is still straight does have a very large oak tree
Section 57	4' long	FEB 2018	repaired by T-3 2018 originally -leans 7" has home owners trash/tools/equipment at wall
Section 58	40' long		leans 1 1/2" This section has pump water system fence within 3' of wall